

### Example

A 10 cm long SMA with circular c/s is preloaded with a weight to induce austenite to martensite phase transformation. The wire is initially at complete austenite phase. The wire is at an ambient temp. of  $25^\circ\text{C}$ . The diameter of the wire is 0.5 mm

$Y_A = 67 \text{ GPa}$	$M_f = 9^\circ\text{C}$	$C_M = 18 \text{ MPa}/^\circ\text{C}$	Resistivity $70 \mu\Omega/\text{cm}$
$Y_M = 26 \text{ GPa}$	$M_s = 18^\circ\text{C}$	$C_A = 14 \text{ MPa}/^\circ\text{C}$	$h_c = 150 \text{ J}/\text{m}^2 \cdot ^\circ\text{C}\cdot\text{s}$
$E_L = 7\%$	$A_s = 35^\circ\text{C}$	$\sigma_{cr}^S = 100 \text{ MPa}$	$\rho = 6450 \text{ kg}/\text{m}^3$
	$A_f = 49^\circ\text{C}$	$\sigma_{cr}^f = 170 \text{ MPa}$	$C_p = 0.2 \text{ kcal}/\text{kg}\cdot^\circ\text{C}$

- (a) Determine the stress required to induce full austenite to martensite phase transformation

$$T_\infty > 25^\circ\text{C} \Rightarrow \sigma_{\text{applied}} = \sigma_{cr}^f + C_M(T - M_s)$$

$$= 170 + 8(25 - 18)$$

$$= 226 \text{ MPa.}$$

- (b) Compute the current reqd. to achieve steady-state temp. of  $75^\circ\text{C}$

$$T_{ss} = T_\infty + \frac{i^2 R}{h_c A_c} \quad R = \text{resistance/length}$$

$$= \frac{76 \times 10^{-6} \times 10^{-2}}{\frac{\pi}{4} (0.5)^2 \times 10^{-6}} = 3.87 \Omega/\text{m}$$

$$i^2 = \frac{(T_{ss} - T_\infty) h_c A_c}{R}$$

$$= \frac{(75 - 25) \times 150 \times \frac{\pi}{4} \times 0.5 \times 10^{-3}}{3.87}$$

$$\Rightarrow i = 1.74 \text{ A}$$

- (c) Find the time taken to start and complete martensite to austenite transformation

$$A_s^x = A_s + \frac{\sigma}{C_A} = 35 + \frac{226}{14} = 51.1^\circ\text{C}$$

$$A_f^x = A_f + \frac{\sigma}{C_A} = 49 + \frac{226}{14} = 65.1^\circ\text{C.}$$

$$t_1 = t_{M \rightarrow A}^S = -t_h \ln \left[ \frac{T_{ss} - T_d}{T_{ss} - T_\infty} \right] = 3.40 \text{ s} = 4.61 \text{ s}$$

$$t_2 = t_{M \rightarrow A}^f = -t_h \ln \left[ \frac{75 - 65.1}{75 - 25} \right] = 7.47 \text{ s}$$

$$t_h = \frac{\rho A C_p}{h_c A_c}$$

$$= \frac{6450 \times \frac{\pi}{4} \times (0.5)^2 \times 10^{-6} \times 0.2 \times 4185}{150 \times \frac{\pi}{4} \times 0.5 \times 10^{-3}}$$

(d) Assuming that the current is set to zero when the material completes  
 $M \rightarrow A$  phase transformation, plot

(i) Temp vs. time (ii)  $\epsilon$  vs. time (iii) strain vs. time for  $t$  0 to 30s

(i) Temp vs. time

heating

$$T(t) = \frac{R}{hcA_c} i^2 (1 - e^{-t/t_h}) + T_{\infty}$$

$$= \frac{3.87 \times (1.74)^2}{150 \times \pi \times 0.5 \times 10^{-3}} (1 - e^{-t/4.61}) + 25$$


$$= 25 + 50(1 - e^{-t/4.61}) \quad 0 \leq t \leq 7.47$$

cooling

$$T(t) = T_{\infty} + (T_0 - T_{\infty}) e^{-t/t_h}$$

$$= 25 + (65.1 - 25) e^{-t/4.61}$$

$$= 25 + 40.1 e^{-t/4.61}$$



(ii)  $\xi_3$  vs. time

$$\xi_3 = 1 \quad 0 \leq t \leq 3.40 \text{ s}$$

$$\xi_{M \rightarrow A} = \frac{1}{2} \left[ \cos \left\{ \frac{\pi}{A_f - A_s} (T - A_s^*) \right\} + 1 \right] \quad 3.40 \leq t \leq 7.47$$


$$\xi_3 = 0 \quad 7.47 \leq t \leq t_3$$

$$\xi_{A \rightarrow M} = \frac{1}{2} \left\{ \cos \frac{\pi}{\nu_{cr}^s - \nu_{cr}^f} \left[ \nu - \nu_{cr}^f - c_M (T - M_s) \right] \right\} + \frac{1}{2}$$

$$M_s^* = \frac{\nu - \nu_{cr}^s}{c_M} + M_s = \frac{226 - 100}{8} + 18 = 33.75^\circ\text{C} \quad \text{for } t \gg t_3$$

$$M_f^* = \frac{\nu - \nu_{cr}^f}{c_M} + M_f = 25^\circ\text{C} \quad (T_\infty)$$

$$t_3 = -t_n \ln \left[ \frac{M_s^* - T_\infty}{T_0 - T_\infty} \right] = -4.61 \ln \left[ \frac{33.75 - 25}{65.1 - 25} \right] = 7.02 \text{ (} +7.47 \text{)} = 14.49 \text{ s.}$$



(iii) Strain vs. time

